

SECRET

OUT56912

S E C R E T 140023Z

1965 OCT 14 00 32Z

25X1

1. CAMERA B 23 WAS USED IN MISSION 8049 FLOWN ON 12 OCTOBER 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EVALUATION OF EXPOSURE AND RESOLUTION IS NOT POSSIBLE. NINETY PERCENT OF THE PHOTOGRAPHY CONSISTS OF SOLID CLOUD COVER AND HAZE DEGRADES THE REMAINING TEN PERCENT.

B. 9R SIDE: FRAME 472 CONTAINS A BLISTER. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 581. FRAME 626 CONTAINS AN EMULSION DEFECT.

C. 9L SIDE: FRAME 526 CONTAINS A MANUFACTURER'S SPLICE. BREAKDOWN SPLICES ARE POSITIONED BETWEEN FRAMES 659/660 AND 867/868.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 1048. BOTH EDGES OF THE FILM EXHIBIT STATIC DISCHARGE TRACES. ROLLER INDUCED DISCHARGE TRACES ARE PRESENT ON THE INBOARD EDGES. PIN HOLES ARE PRESENT INTERMITTENTLY THROUGHOUT THE MATERIAL.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FAULTS.

3. POSITIVE:

A. THE PI SUITABILITY IS POOR.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURED 90 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

S E C R E T

--END OF MESSAGE--

SECRET

14 OCT 1965

COPIES RECEIVED

Office	Act.
File	
OS	
ADMIN	
SEC BR	
PCDS	
CSD	
IPB	
PD	
PSD	
PSD-ICB	
TID	✓
PID	
PAG	
DIAXX 4	
SPAD	
NSA-LO	
DIA-AP	

Declassification Review by NGA/DoD